


PANNING SYSTEM - 2 3/8" FRAME DEPTH



TYPICAL PANNING JAMB

STRUCTURAL MULLION


TYPICAL PANNING JAMB



MAIL: P.O. Box 3202
 Sioux City, Iowa 51102
 PHONE: (402) 494-6000
 FAX: (402) 494-6765
 WEBSITE: www.gerkin.com
 E-MAIL: gerkin@gerkin.com

©2012 GERKIN.COM

PANNING SYSTEM - 2 3/8" FRAME DEPTH



TYPICAL PANNING HEAD

TYPICAL PANNING SILL

GERKIN WINDOWS & DOORS RESERVES THE RIGHT
 TO CHANGE OR DISCONTINUE MANUFACTURING ANY
 OF ITS STANDARD WINDOW SYSTEMS OR COMPONENTS
 WITHOUT PRIOR WRITTEN NOTICE.



MAIL: P.O. Box 3202
 Sioux City, Iowa 51102
 PHONE: (402) 494-6000
 FAX: (402) 494-6765
 WEBSITE: www.gerkin.com
 E-MAIL: gerkin@gerkin.com

©2012 GERKIN.COM